Recording District 301 Anchorage 08/11/2017 03:01 PM Page 1 of 2




<u>La</u>	<u>nd Su</u>	rvey Monument Record	Rev. Feb 2002
1)	X	Land Corner Restoration  Land Corner Establishment	
		Other:	
2) Boss	establisl	tion of corner evidence found or a concise st h the corner: West 1/4 corner of Section 12 and Section Corne	
		West, Seward Meridian. Proportioned bewteen t	
	.,		

Description of monument and accessories established to perpetuate the location of the

A sketch showing the relative location of monument and reference points or a sketch showing the monuments used and the measurements made to determine the position of the monument being established. (Use additional sheets if necessary)

Set 1-1/4" Yellow Plastic Cap on 5/8" x 30" Rebar, 0.1' above grade, stamped LS14444.



3)

monument.

S 1/16 Corner, Sec 12, T11N, R3W, SM, AK

## Surveyor's Certificate and Stamp

do hereby certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Date July 25, 2017



## **Corner Description**

Potter Cree	k		S	ubdivision,
Section 12	, Township	11N	_, Range 3W	
Seward	Meric	dian, Alaska. Da	ate Filed 8-27-197	l
Recorder's N			Record	
If unsurvey	red, include protra	acted section nu	mber.	
Ancho	rage	_	8)	
Recording District			• = Loc	ation of Mo
				1" = 1 Mi
		]	ndex Ref. No.	
(DO NOT FILL IN)		_		
(DO	•			
·	·			
(DO Return to:	Taylor Moore			-
·	Taylor Moore Enterprise En	ngineering, Inc.		<b>-</b> -



Page 2 of 2